Build Your Own Clone Classic Compressor Kit Instructions



Warranty:

BYOC, LLC guarantees that your kit will be complete and that all parts and components will arrive as described, functioning and free of defect. Soldering, clipping, cutting, stripping, or using any of the components in any way voids this guarantee. BYOC, LLC guarantees that the instructions for your kit will be free of any majors errors that would cause you to permanently damage any components in your kit, but does not guarantee that the instructions will be free of typos or minor errors. BYOC, LLC does not warranty the completed pedal as a whole functioning unit nor do we warranty any of the individual parts once they have been used. If you have a component that is used, but feel it was defective prior to you using it, we reserve the right to determine whether or not the component was faulty upon arrival. Please direct all warranty issues to:

sales@buildyourownclone.com This would include any missing parts issues.

Return:

BYOC, LLC accepts returns and exchanges on all products for any reason, as long as they are unused. We do not accept partial kit returns. Returns and exchanges are for the full purchase price less the cost of shipping and/or any promotional pricing. Return

shipping is the customers responsibility. This responsibility not only includes the cost of shipping, but accountability of deliver as well. Please contact sales@buildyourownclone.com to receive a return authorization before mailing.

Tech Support:

BYOC, LLC makes no promises or guarantees that you will sucessfully complete your kit in a satisfactory mannor. Nor does BYOC, LLC promise or guarantee that you will receive any technical support. Purchasing a product from BYOC, LLC does not entitle you to any amount of technical support. BYOC, LLC does not promise or guarantee that any technical support you may receive will be able to resolve any or all issues you may be experiencing.

That being said, we will do our best to help you as much as we can. Our philosophy at BYOC is that we will help you only as much as you are willing to help yourself. We have a wonderful and friendly DIY discussion forum with an entire section devoted to the technical support and modifications of BYOC kits.

www.buildyourownclone.com/board

When posting a tech support thread on the BYOC forum, please post it in the correct lounge, and please title your thread appropriately. If everyone titles their threads "HELP!", then it makes it impossible for the people who are helping you to keep track of your progress. A very brief discription of your specific problem will do. It will also make it easier to see if someone else is having or has had the same problem as you. The question you are about to ask may already be answered. Here are a list of things that you should include in the body of your tech support thread:

- 1. A detailed explanation of what the problem is. (not just, "It doesn't work, help")
- 2. Pic of the top side of your PCB.
- 3. Pic of the underside of your PCB.
- 4. Pic that clearly shows your footswitch/jack wiring and the wires going to the PCB
- 5. A pic that clearly shows your wiring going from the PCB to the pots and any other switches(only if your kit has non-PC mounted pots and switches)
- 6. Is bypass working?
- 7. Does the LED come on?
- 8. If you answer yes to 6 and 7, what does the pedal do when it is "on"?
- 9. Battery or adapter.(if battery, is it good? If adapter, what type?)

Also, please only post pics that are in focus. You're only wasting both parties' time if you post out of focus, low res pics from your cell phone.

Revision Notes:

Rev 1.0 There are no known errors.

Copyrights:

All material in this document is copyrighted 2011 by BYOC, LLC



Parts Checklist	page 4 - 5
Populating the Circuit Board	page 6 - 16
Main PCB Assembly	page 17 - 19
Wiring	page 20 - 23
Installing the IC and Finishing Up	page 24
Operation Overview	page 25
Schematic	page 26 - 27

b.y.o.c / effects

Parts Checklist for BYOC Classic Compressor Kit

Resistors:

- 1 4k7 (yellow/purple/black/brown/brown)
- 6 10k (brown/black/black/red/brown)
- 1 15k (brown/green/black/red/brown)
- 2 27k (red/purple/black/red/brown)
- 1 56k (green/blue/black/red/brown)
- 2 150k (brown/green/black/orange/brown)
- 2 220k (red/red/black/orange/brown)
- 3 470k (yellow/purplw/black/orange/brown)
- 4 1M (brown/black/black/yellow/brown)

Capacitors:

- 1 220pf (221) ceramic disc (small round orange)
- 1 1n0 or .001μ (102 or 1nj100, 1nj63, ect.)
- $5 10n \text{ or } .01\mu \text{ film } (103)$
- 1 47n or $.047\mu$ film (473)
- 6 1μ aluminum electrolytic
- 1 10µf aluminum electrolytic
- 1 100µf aluminum electrolytic

Diodes:

2 - 1N4148 (small orange glass with black stripe)

Transistors:

5 - 2N5088, 2N3904, or 2N2222


IC's:

- 1 CA3080E
- 1 8 pin socket

VINTAGE UPGRADE PACK (sold separately):

- 1 CA3080A (TO-100 metal can IC)
- 1 TO-100 8 pin socket
- 5 2SC1849 transistors

Potentiometers: Be sure to snap off the small tab on the side of each panel mounted pot.



linear (LEVEL)

- 1 A100k linear (LEVEL)
- 1 B500k audio (SENSITIVITY)
- 1 2k trimpot


Hardware:

- 1 drilled enclosure w/ 4 screws
- 1 byoc classic compressor PCB
- 1 3PDT footswitch
- 2 knobs
- 1 AC adaptor jack
- 1 1/4"mono jack
- 1 1/4"stereo jack
- 1 red LED
- 1 battery snap
- 4 bumpers


hook-up wire




Populating the Circuit Board




STEP 1: Add the diodes. Be sure to match the end of the diode with the stripe to the layout on the PCB. The stripped end should go in the square solder pad.



STEP 2: Add the resistors . Resistors are not polarized, so it does not matter which end goes in which solder pad. Take your time and be sure not to confuse similarly banded resistors such as the 470k with the 4k7 or the 10k with the 100k. If you have difficulty reading the color bands, use a digital multimeter to test the value of each resistor.



Step 3: Add the trim pot. The space on the PCB has 5 holes, but the trim pot will only have 3 leads. This is so that the PCB can accept a variety of different brands and styles of trim pot. There should only be 1 way that your trim pot will fit into the PCB without having to bend the leads.



8 pin IC socket. **ONLY SOLDER THE SOCKET! NOT THE ACTUAL IC!** This is a socket. The socket gets soldered to the PCB. The ICs get inserted into the sockets. The actual IC chip itself, never gets soldered. You will insert the IC into the socket after the entire pedal has been built.


STEP 4: Add the 8 pin IC socket. **ONLY SOLDER THE SOCKET! NOT THE ACTUAL IC!** This is a socket. The socket gets soldered to the PCB. The ICs get inserted into the sockets. The actual IC chip itself, never gets soldered. You will insert the IC into the socket after the entire pedal has been built.

See page 21 for instructions on how to install the IC into the socket.

If installing the DIP8 socket for the CA3080E chip, orient the socket so that the u-shaped notch in the socket matches the layout on the PCB highlighted in red.


If installing the TO-100 socket for the CA3080A chip(sold separately), orient the socket so that the tab on the socket lines up the with layout on the PCB highlighted in purple.

NOTE: You can have both sockets installed at the same time. This way you can experiment with the different ICs.




Step 5: Add the Transistors. Be sure to orient the transistors so that the flat side of the tansistor body matches up with the flat side on the PCB layout. This is the same for both the 2N5088 and 2SC1849 or any transistor that is supplied with this kit.

NOTE: This PCB is designed with the standard EBC pinout. Both the 2N5088 and 2SC1849 transistors that are supplied with BYOC kits have the standard EBC pinout. However, some brands of 2SC1849 have a BCE pinout. If you have sourced transistors from somewhere other than BYOC, be aware of your transistors' pinouts.




Step 6: Add the film and ceramic disc capacitors. These are not polarized and can be inserted into the PCB either way.




STEP 7: Add the aluminum electrolytic capacitors. These are polarized. The positive end will have a longer lead and should go in the square solder pad. The negative end will have a shorter lead with a black or white stripe running down the body of the capacitor.

Install the capacitor highlighted in yellow with the long lead inserted into the round hole.




Step 8: Add the battery snap. Thread the solder ends of the battery snap into the strain relief holes from the bottom solderside of the PCB and out through the top. Insert the solder ends of the battery snap wires into the topside of their respective solder pads. Solder on the bottom side of the PCB. Remember the red wire goes in the "+" hole and the black wire goes in the "-" hole.




Step 8: Add wires to the IN, OUT, RING, and two Ground eyelets. Start by cutting four 2.5" pieces of wire and one 1.5" piece of wire. Strip 1/4" off each end and tin the ends. Tinning means to apply some solder to the stripped ends of the wires. This keeps the strands from fraying and primes the wire for soldering. Solder a 2.5" piece of wire to each of the IN, OUT, and Ground eyelets on the PCB. Solder the 1.5" piece of wire to the RING eyelet on the PCB. Load the wires in from the top and solder on the bottom of the PCB.

Main PCB Assembly




Step 1: Mount the DC adapter jack to the enclosure.


The sleeve disconnect terminal of the DC adapter jack connects directly to the positive terminal of the battery via the PCB. The sleeve disconnect terminal is connected to the sleeve terminal when there is no DC adapter plugged into the jack. When a DC adapter jack is plugged into the DC adapter jack, the connection between the sleeve disconnect terminal and the sleeve terminal is broken, thus disconnecting the batter from the circuit when a DC power supply is in use. This allows you to safely keep a battery in your pedal and still use a DC power supply.



Step 2: Connect the TIP (negative) terminal of the DC adaptor jack to the "-" eyelet on the PCB with 2 inches of hook up wire. Connect the SLEEVE of the DC adaptor jack to the "+" eyelet on the far right side of the PCB with 2 inches of hook up wire. Connect the battery disconnect terminal of the DC adaptor jack to the "+" eyelet more towards the center of the PCB with 2" of hookup wire. Load the wires in from the bottom of the PCB and solder on the topside.



Step 3: Flip the PCB over so that the bottom or solder side is up. Insert the A100k(LEVEL), B500k(SUSTAIN) potentiometers, and the LED into the bottom side of the PCB. DO NOT SOLDER ANYTHING YET!!! The LED will have one lead that is longer than the other. The longer lead goes in the hole with the square solder pad.




Step 4: Hold the PCB in one hand so that the component side of the PCB is in the palm of your hand and the bottom side with the pots, toggle switch and LED is facing up. Now use your other hand to guide the predrilled enclosure onto the PCB assembly so that the pots and LED all go into their respective holes. Once the PCB assembly is in place, secure it by screwing on the washers and nuts for the pots and toggle switch. Only tighten them with your fingers. You do not want them very tight yet. Be sure to keep your hand on the PCB so that it does not fall off the PC mounting posts of the pots and toggle switch.

Step 5: Turn the entire pedal over so that the component side of the PCB if facing up. Lift the PCB up off the pots and toggle switch about 2mm just to make sure that the back of the PCB does not short out against that pots. Make sure the PCB is level and symetrically seated inside the enclosure.

Step 6: Solder the pots and LEDs. You will solder these parts on the component side of the PCB. After you have soldered them in place, be sure to tighten up their nuts.





Step 1: Install the 1/4" jacks to the enclosure.




Step 2: Install the footswitch. Orient the footswitch so that the flat sides of the solder lugs are like the diagram below. NOTE: There are no actual number markings on the footswitch. There are two correct ways you can orient the footswitch. They are both 180 degrees of each other. Either way is fine. It does not matter as long as the flat sides of the solder lugs are running horizontal, not vertical.

Footswitch Solder Lug Designations







Step 3: Connect the pre stripped and tinned wires to the 1/4" jacks. Step 4:

- Cut 4 x 3/4" pieces of wire. Strip 1/8" off each end. These will be used to connect lugs/eyelets 1, 2, 7, & 8
- Cut 1 x 1" piece of wire. Strip 1/8" off each end. This will be used to connect lug/eyelet 5
- Cut 1 x 1.5" peice of wire. Strip 1/8" of one end. Strip 1/2" off the other end. This will be used to connect lug/eyelet 4. The longer stripped end will be used to jumper


- lug 4 to 9.
- Cut 3 x 2" pieces of wire. Strip 1/4" off each end. These will be used to connect the tip and sleeve of the IN jack and the tip of the OUT jack to the PCB.
- Cut 1 x 1.5" peice of wire. Strip 1/4" off each end. This will be used to connect the ring of the IN jack to the ring eyelet on the PCB.


Step 5: Solder one end of the pre-cut and pre-stripped wires to the footswitch.

Step 6: Insert the other remaining ends of the pre-cut and pre-stripped wires into the topside of the PCB and solder. You can can solder these on the topside as well. It is easier this way, but you may burn a small amount of the PVC coating on the wires. This is purely asthetic and won't damage the wires in anyway. But you can avoid this by removing the PCB assembly and footswitch from the enclosure entirely (the PCB assembly will still be attached to the enclosure via the DC jack wiring) so that you have access to solder the underside of the PCB.

Installing the IC and Finishing Up

If your IC has both a notch and dot, always refer to the notch and ignore the dot.






Once you've install the IC, it's time to test the pedal. If you don't get any sound at first, don't worry. You will need probably need to adjust the trimpot. If your trimpot isn't already set at the middle of its rotation, do so. This may or may not be the optimal setting for the trimpot, but it should definitely produce sound and be a good starting point for fine tuning.

You should adjust the trimpot to the position where you get the least amount of distortion when playing your guitar and where you get the longest smoothest decay. This may take a few minutes and several adjustments. You should still get a very small amount of pleasing distortion. It's just the nature of the circuit. It is not perfectly clean, but the distortion does give it some warmth and is part of the pedals character. If you have an 18v adapter, we recommend using it while adjusting your trimpot. It makes the trimpot much more sensitive and easier to dial in. 18v will also increase headroom and reduce distortion.

Don't forget to put the cover on the enclosure and apply the bumpers to the cover if you'd like to use them.

Operating Overview




LEVEL & SUSTAIN: Do you really need an explaination of what these knobs do?

DC power supply - Use a 2.5mm negative tip (this is your standard guitar fx style adapter) 9, 12, 15, or 18VDC adapter. The higher voltage will give you more headroom and output. If using battery power, only use a single 9V battery.

Current Draw - 5mA

Input Impedance - 470k ohms

Output Impedance - 100k ohms



Please visit http://buildyourownclone.com/board for any technical support

copyright 2010 B.Y.O.C., LLC